# Cape Trib Road & Cape Trib Bloomfield Road



**Community Reference Group** 

Date: Thursday 28 August 2025

Venue: Via Teams Time: 10:00am

### **Attendees**

### Abi Ralph

- Gaye Scott
- Owen Sellwood
- Robyn Guedes

# **Apologies**

- Steve Sponberg
- Gabriel Nucifora

# **Road Update**

Gaye presented the road update.

# **Cape Tribulation Bloomfield Road**

### **Unsealed Sections**

- Durack has commenced at Degarra end on repair of unsealed sections
- Gravel section between the concreted Pierce's Hill and the bitumen heading north to Wujal has deteriorated catastrophically.
- Contractor has been advised to grade the surface to keep it safe and trafficable.

#### **Concrete Section**

- Contractor encountered mass debris under the area where the concrete road is being reinstated.
- This was debris pulled back into the site to reinstate the washed away formation.
- This has delayed expected completion to late September 2025.
- NCP Contracting commenced watering operations on the sealed road fronting 2529 Cape
  Tribulation Bloomfield Rd.
- Hasn't really helped. Team working on a solution.

### Landslips - HEH

- Work progressing on three of the 10 sites
- Completion is expected by mid December 2025.

# **Roadside Vegetation**

- Roadside vegetation clearing will be done on both Donovans and Cowrie Ranges.
- Work will start 1 September and continue until both ranges are completed.

#### **Other Northern Roads**

- Banabilla, Evergreen and Idriess Work will commence first week in October
- Zig Zag Work to commence 28 August 2025
- Concrete section China Camp Road tenders close this week.

# **Noah Range Landslip**

- Work progressing as planned
- Completion expected by March 2026.

## **Noah Creek Bridge**

- The large, custom-made timber girders have been ordered and are due to arrive on site late
  September 2025
- The repairs are being funded by QRA.
- The construction method and its impact on functionality of bridge is still being worked through.
- QRA has confirmed funding for the temporary bypass and the new bridge.
- The construction of both the bypass and new bridge are scheduled for the 2026 dry season.
- The alternative methodology raised by Lawrence M was considered, and if starting from scratch, it may have been an option, but it is not compatible with having to incorporate the existing concrete blocks into the final structure.

### **Noah Creek Causeway**

- HEH has a machine on site at the causeway to carry out repairs in a timely manner.
- In a move to improve communications, when the causeway has to be closed, HEH provides instructions to FNQ Traffic Control to erect road closed signs and remove the signs as required.
- FNQ Traffic Control will alert Gaye Scott who can send out an alert.

# **Landslips South of Daintree River**

COLPO has commenced repairs at two locations on Upper Daintree Road.

### **Taylors and Lees Bridges**

Work has commenced at Lees Bridge with the delivery of rock and site establishment. Work on Taylors Bridge to start 11 September.

### **Carried Forward**

Daintree Discovery Centre – work has been completed

Turpentine Road – no update re timeframe as yet

**Betterment Funding** – Verbal advice from QRA on some. Keep on the agenda until QRA confirms.

**Concrete Pavement – CTBR Degarra –** Gaye S to clarify whether rock protection in the gully beside the road is included in the scope of works.

**Luana Hairpin**. Confirm whether the landslips on the switchback/Luana Hairpin are included in works, namely the narrowing on the first bend heading south from Luana Creek and the narrowing halfway up. Gaye S to report back.

**Escort Vehicles – Alexandra Range -** Clarify whether vehicles over 19 metres need escort vehicles. Gabe N to check.

### **New Business**

# **Dust Issues & Vehicle Speed - Rykers Road.**

- There have been recent sightings of an adult cassowary with two chicks and a tree kangaroo on Rykers Road.
- Delivery driver arrived at Cape Trib Beach House badly shaken up which he said was due to speed of passing truck.
- Exiting Cape Trib Beach House requires waiting several minutes for dust to settle to be safe.
- Vehicles involved in the repair of landslips on Cape Tribulation Bloomfield Road appear to be travelling at a cracking pace.
- Information was passed onto the contractor who raised the issue at their daily pre-start meeting to remind all staff about the speed limit and to slow down and also instructed its water cart to put more focus into this particular section.

# **Next Meeting**

■ Thursday 11 September 2025

3|Page